

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re patent of:

BURNS *et al.*

Patent No.: 7,449,908 B2

Issued: November 11, 2008

For: **Process Monitor for Monitoring
an Integrated Circuit Chip**

Confirmation No.: 2309

Atty. Docket: 1875.3770001

Request for Certificate of Correction under 37 C.F.R. § 1.322

Attn: Certificate of Correction Branch

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

Sir:

It is hereby requested that a Certificate of Correction under 37 C.F.R. § 1.322 be issued for the above-captioned United States Patent. This Certificate of Correction is being requested due to a mistakes which appear in the printed patent. These mistakes were made by the U.S. Patent and Trademark Office.

Specifically, the printed patent contains the following errors for which a Certificate of Correction is respectfully requested:

Column 20, line 47, "the set of" should be replaced with --the set of:--.

Column 21, line 17, "wherein the at digitized signal" should be replaced with --wherein the digitized signal--.

Column 22, line 11, "the set of" should be replaced with --the set of:--.

Support for the corrections can be found in the Amendment filed

April 14, 2008.

Remarks


The above-noted corrections do not involve such changes in the patent as would constitute new matter or would require reexamination.

A completed Form PTO/SB/44 accompanies this request, with the above-noted correction printed thereon. Accordingly, a Certificate of Correction is believed proper and issuance thereof is respectfully requested.

The Commissioner is hereby authorized to charge any fee deficiency, or credit any overpayment, to our Deposit Account No. 19-0036.

Respectfully submitted,

STERNE, KESSLER, GOLDSTEIN & FOX P.L.L.C.

A handwritten signature in black ink, appearing to read "Lori A. Gordon".

Lori A. Gordon
Attorney for Applicants
Registration No. 50,633

Date: January 16, 2009

1100 New York Avenue, N.W.
Washington, D.C. 20005-3934
(202) 371-2600

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,449,908 B2
DATED : November 11, 2008
INVENTOR(S) : BURNS et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 20, line 47, "the set of" should be replaced with --the set of:--.

Column 21, line 17, "wherein the at digitized signal" should be replaced with --wherein the digitized signal--.

Column 22, line 11, "the set of" should be replaced with --the set of:--.

MAILING ADDRESS OF SENDER:

Sterne, Kessler, Goldstein & Fox P.L.L.C.
1100 New York Avenue, N.W.
Washington, DC 20005-3934

PATENT NO. 7,449,908 B2

No. of additional copies

⇒ 0

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. **SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.**

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.